

SC CREW GORE-TEX OUTERWEAR

LAUNDERING AND CARE

GENERAL CARE

- Hang all wet garments to dry after each use in rain or after laundering.
- Do not leave wet garments balled up in bag or locker.
- **DO NOT DRY CLEAN YOUR OUTERWEAR**

WASHING

- Garments should be washed in cold water. Rinse temperature should not exceed wash cycle by more than 10 degrees.
- Wash with mild detergent (pH under 10.0) i.e. Tide (without bleach)
- Do not use chlorine bleach or any form of bleaching agent, whitener, brighter or laundry booster.

DRYING

- For best results garments should be hung to drip dry.
- When tumble drying use lowest temperature or "air setting".
- Remove garments immediately after drying.

RESTORING WATER-REPELLENCY

- After numerous instances of wearing of your garment in the rain or washing you may notice the water is not "BEADING" as much on the fabric. Your Teflon HT finish is not gone; it's simply absorbed into the shell fabric.
- TO RESTORE THE "BEADING" QUALITY: Place your garment in a dryer, on medium temperature, (100 degrees) for 10 minutes or iron your garment at very low temperature with a towel between the garment and the iron.

ANY QUESTIONS?

- Call us at (800) 875-1883 or e-mail us at info@boathouse.com